

UNIT NAME C-337-A VaporizerREGULATORY STATUS Spill site, CERCLALOCATION East side of C-337 building (Map location 71)APPROXIMATE DIMENSIONS UnknownFUNCTION UF₆ vaporization facilityOPERATIONAL STATUS ActiveDATES OPERATED 1958(?) to present

SITE/PROCESS DESCRIPTION: UF₆ cylinders are placed in autoclaves and vaporized by steam heating

WASTE DESCRIPTION: During an autoclave replacement project it was discovered that hydraulic oils containing PCBs had leaked from the oil system onto the concrete and into drain lines along with steam condensate. Some material was removed through excavation, but some PCBs remain in the soil.

WASTE QUANTITY: Unknown

DESCRIPTION OF RELEASE: Known releases to the soil and sewer lines in the area. PCBs and oil were released.

DOCUMENTATION OF NO RELEASE:

RFI NECESSARY: