

**PRELIMINARY ASSESSMENT/SITE INSPECTION REPORT
AND SWMU ASSESSMENT REPORT**

UNIT NUMBER: 388

UNIT NAME: C-416 Decontamination Pad

DATE: 01/19/01

REGULATORY STATUS: SWMU

LOCATION: North of C-631

APPROXIMATE DIMENSION: 30 ft. X 50 ft.

FUNCTION: Decontamination of drilling equipment and storage of waste associated with the decontamination process.

BRIEF HISTORY: According to GEO Consultants, LLC personnel, this area was established as a decontamination area for equipment associated with various environmental site investigations.

OPERATIONAL STATUS: Active.

DATES OPERATED: According to GEO Consultants, LLC personnel, this decon pad was probably built in the late 1980s.

SITE/PROCESS DESCRIPTION: Concrete pad with sump. Also, 1000-gallon poly tanks are located here to store sump water.

WASTE DESCRIPTION: Decon water and PPE. According to GEO Consultants, LLC personnel, in addition to the decontamination function, this pad was used to store material and equipment, potentially contaminated with PCBs.

WASTE QUANTITY: As of 1/9/00, there was one 55-gallon drum of material removed from the sump and the rainwater that had collected in the sump. According to GEO Consultants, LLC personnel, three 1000-gallon poly tanks of sump/decon water are sometimes stored here.

SUMMARY OF ENVIRONMENTAL SAMPLING DATA: None

DESCRIPTION OF RELEASE AND MEDIA AFFECTED: According to GEO Consultants, LLC personnel there have been no releases from this SWMU to the environment.

GROUNDWATER: N/A

SURFACE WATER: N/A

SOIL: N/A

ECOLOGY AFFECTED (i.e., endangered/threatened species): None

DOCUMENTATION OF NO RELEASE: According to GEO Consultants, LLC personnel, inspection checklists are on file documenting that there have been no releases from this SWMU.

IMPACT ON OR BY OTHER SWMU/AOC: There was no evidence of any impact on or by any other SWMU.

PRG COMPARISON: N/A

RFI NECESSARY No. This unit is being proposed for No Further Action since it has had no releases to the environment and is not a threat to human health and the environment. According to GEO Consultants, LLC personnel, this unit has been managed and inspected in accordance with approved procedures since its creation.

NOTE: Elements included in this outline shall be considered and incorporated, as appropriate, when developing the above referenced document.