

UNIT NUMBER 11

UNIT NAME C-400 Trichloroethylene Leak Site

REGULATORY STATUS Spill site, 3004(u)

LOCATION Southwest corner of C-400 (Map location 11)

APPROXIMATE DIMENSIONS Unknown

FUNCTION None

OPERATIONAL STATUS None

DATES OPERATED N/A

SITE/PROCESS DESCRIPTION: In mid-1986 the leakage of trichloroethylene (TCE) from an underground storm sewer was discovered. The TCE was released to the sewer from the C-400 degreaser area. It was not known that the sump discharged to the sewer.




WASTE DESCRIPTION: Trichloroethylene (F001)

WASTE QUANTITY: Unknown

DESCRIPTION OF RELEASE: See Site/Process Description

DOCUMENTATION OF NO RELEASE:

RFI NECESSARY: Yes





11. G-100 Trichloroethylene Leak Site