

UNIT NAME C-728 Motor Cleaning FacilityREGULATORY STATUS 3004(u)LOCATION North of C-720 (Map location 33)

APPROXIMATE DIMENSIONS _____

FUNCTION Motor cleaning unitOPERATIONAL STATUS ActiveDATES OPERATED 1957 to present

SITE/PROCESS DESCRIPTION: Until ~1975, motors were cleaned by dipping in a tank containing mineral spirits. This operation was discontinued and a steam cleaning unit and a water treatment unit were installed.

WASTE DESCRIPTION: Mineral spirits containing grease, oil, and uranium. Aqueous solutions of uranium, NaOH.

WASTE QUANTITY: Unknown

DESCRIPTION OF RELEASE: No information available

DOCUMENTATION OF NO RELEASE: No information available

RFI NECESSARY: Yes