

UNIT NUMBER 62

UNIT NAME C-375-S6 Southwest Ditch

REGULATORY STATUS 3004(u)

LOCATION Southwest area of plant outside security area (Map location 62)

APPROXIMATE DIMENSIONS _____

FUNCTION Surface drainage

OPERATIONAL STATUS Active

DATES OPERATED 1950s to present

SITE/PROCESS DESCRIPTION: Surface drainage ditch

WASTE DESCRIPTION: Storm water, laboratory waste water from C-710 operations, some C-720 effluents

WASTE QUANTITY: Unknown

DESCRIPTION OF RELEASE: No information available

DOCUMENTATION OF NO RELEASE: No information available

RFI NECESSARY: Yes