

UNIT NUMBER 78

UNIT NAME C-420 PCB Spill Site

REGULATORY STATUS CERCLA

LOCATION C-420 Transformer Area (Map location 78)

APPROXIMATE DIMENSIONS Unknown

FUNCTION Spill site

OPERATIONAL STATUS N/A

DATES OPERATED N/A

SITE/PROCESS DESCRIPTION: Spill site resulting from a transformer rupture

WASTE DESCRIPTION: PCBs

WASTE QUANTITY: Unknown

DESCRIPTION OF RELEASE: PCB containing oil was released from a transformer following the failure of the transformer. Some soil was removed and the area covered with asphalt.

DOCUMENTATION OF NO RELEASE:

RFI NECESSARY: Yes