

UNIT NUMBER 79

UNIT NAME C-611 PCB Spill Site

REGULATORY STATUS CERCLA

LOCATION C-611 Transformer area (Map location 79)

APPROXIMATE DIMENSIONS \_\_\_\_\_

FUNCTION Spill Site

OPERATIONAL STATUS N/A

DATES OPERATED Date of release unknown

SITE/PROCESS DESCRIPTION: Spill site

WASTE DESCRIPTION: PCBs

WASTE QUANTITY: Unknown

DESCRIPTION OF RELEASE: Transformer oils containing PCBs were released to soils in the vicinity.

DOCUMENTATION OF NO RELEASE:

RFI NECESSARY: Yes