

UNIT NUMBER 81

UNIT NAME C-541-A PCB Spill Site

REGULATORY STATUS CERCLA

LOCATION C-541-A (Map location 81)

APPROXIMATE DIMENSIONS _____

FUNCTION Spill site

OPERATIONAL STATUS N/A *Unknown*

DATES OPERATED Releases occurred from the 1950s to about 1976

SITE/PROCESS DESCRIPTION: Spill site

WASTE DESCRIPTION: PCBs

WASTE QUANTITY: Unknown

DESCRIPTION OF RELEASE: Transformer oils containing PCBs were released to soils in the area.

DOCUMENTATION OF NO RELEASE

RFI NECESSARY: Yes