

UNIT NUMBER 83

UNIT NAME C-533 Switchyard

REGULATORY STATUS CERCLA

LOCATION C-533 (Map location 83)

APPROXIMATE DIMENSIONS 390' x 690'

FUNCTION Electrical transformer and switchyard

OPERATIONAL STATUS ~~NA~~ Active

DATES OPERATED 1951 to present

SITE/PROCESS DESCRIPTION: Chlorinated solvents were used to clean the external surfaces of transformers and switchgear.

WASTE DESCRIPTION: Chlorinated solvents, PCBs

WASTE QUANTITY: Unknown

DESCRIPTION OF RELEASE: See Site/Process Description

DOCUMENTATION OF NO RELEASE: No information

RFI NECESSARY: Yes