

UNIT NUMBER 84

UNIT NAME C-535 Switchyard

REGULATORY STATUS CERCLA

LOCATION C-535 (Map location 84)

APPROXIMATE DIMENSIONS 430' x 460'

FUNCTION Electrical switchyard

OPERATIONAL STATUS ~~IN~~ Active

DATES OPERATED 1953 to present

SITE/PROCESS DESCRIPTION: Chlorinated solvents were used to clean exterior surfaces of electrical equipment.

WASTE DESCRIPTION: Chlorinated solvents, PCBs

WASTE QUANTITY: Unknown

DESCRIPTION OF RELEASE: See Site/Process Description

DOCUMENTATION OF NO RELEASE:

RFI NECESSARY: Yes