

UNIT NUMBER 92

UNIT NAME Fill Area for Dirt from C-420 PCB Spill Site

REGULATORY STATUS: CERCLA

LOCATION: North of C-331, west of water towers

APPROXIMATE DIMENSIONS: Unknown

FUNCTION: N/A

OPERATIONAL STATUS: N/A

DATES OPERATED: NA

SITE/PROCESS DESCRIPTION: PCB contaminated soil from transformer failure (August 1967) at C-420 area was transported to this location and spread on the ground as fill material.

WASTE DESCRIPTION: PCBs

WASTE QUANTITY: Unknown

DESCRIPTION OF RELEASE: PCB contaminated soil spread and used as fill

DOCUMENTATION OF NO RELEASE: N/A

RFI NECESSARY: Yes