

UNIT NUMBER 96

UNIT NAME Cooling Tower Scrap Wood Pile

REGULATORY STATUS: CERCLA/RCRA

LOCATION: Near southwest corner of C-333 building

APPROXIMATE DIMENSIONS: \_\_\_\_\_

FUNCTION: Temporary storage of scrap wood from cooling tower

OPERATIONAL STATUS: ~~Active~~ Inactive

DATES OPERATED: 1988 Present - 1997

SITE/PROCESS DESCRIPTION: Disassembled cooling towers and packaged, bundled, and stacked the wood on a concrete pad and covered with hypalon.

WASTE DESCRIPTION: Preliminary sample results indicate the wood contains pentachlorophenol and detected levels of total dioxins and furans.

WASTE QUANTITY:

DESCRIPTION OF RELEASE: None documented

DOCUMENTATION OF NO RELEASE: None documented

RFI NECESSARY: Undecided