

UNIT NUMBER SWMU 97

UNIT NAME C-601 Diesel Spill

REGULATORY STATUS: AOC (CERCLA)

LOCATION: East Side of C-600

APPROXIMATE DIMENSIONS: Unknown

FUNCTION: Diesel fuel storage tanks

OPERATIONAL STATUS: Active

DATES OPERATED: 1951 - present

SITE/PROCESS DESCRIPTION: Storage tanks for storage of fuel oil

WASTE DESCRIPTION: Diesel fuel constituents were observed in soils during the Phase II investigation

WASTE QUANTITY: Unknown

DESCRIPTION OF RELEASE: On March 9, 1979 a spill of approximately 17,000 gal. of no. 2 fuel oil occurred at the C-601 fuel oil tank area. Refer to the Phase II report for concentrations of contaminants in the soil.

DOCUMENTATION OF NO RELEASE: N/A

RFI NECESSARY: YES

This unit underwent a prioritized RFI under the CERCLA ACO. It was determined that it was not a source of Off-site contamination. However, Polycyclic Aromatic hydrocarbons were detected at up to 8 parts per million from the Phase II Site Investigation under an Administrative Consent Order. PCB was detected in a sample at less than one part per million. See the Phase II Investigation Report for additional details. This unit will be further addressed with WAG 9 in accordance with the RFI schedule outlined in the HSWA Permit.