

UNIT NUMBER SWMU 103

UNIT NAME Rubble Pile 1

REGULATORY STATUS:- AOC

LOCATION: Entrance Highway at Dykes Road S-8200 W-4400

APPROXIMATE DIMENSIONS: Approx. 250 ft long, 12 ft deep, and 20 ft wide

FUNCTION: Used in construction of fish pond for wildlife area

OPERATIONAL STATUS: active

DATES OPERATED: from about 1978 to present

SITE/PROCESS DESCRIPTION: None

WASTE DESCRIPTION: Dirt, gravel, and concrete spoil from construction of  
cylinder storage yard south of C-333

WASTE QUANTITY: Unknown, total dam volume about 2500 cu yds - concrete visible  
at NW corner only

DESCRIPTION OF RELEASE: N/A

DOCUMENTATION OF NO RELEASE: Beta/Gamma scan found no elevated readings on  
rubble. Gamma soil survey showed no above  
criteria concentrations in soil around rubble.

RFI NECESSARY: YES



