

UNIT NUMBER SWMU 106

UNIT NAME Rubble pile 4

REGULATORY STATUS: AOC --

LOCATION: East of Dykes Road S-2200 W-0700

APPROXIMATE DIMENSIONS: Dam approx. 25 ft long and 15 ft wide - concrete in  
and on dam face

FUNCTION: Provides skimming and sampling of ditch drainage

OPERATIONAL STATUS: active

DATES OPERATED: Unknown

SITE/PROCESS DESCRIPTION: None

WASTE DESCRIPTION: Concrete slabs from plant road construction spoils

WASTE QUANTITY: Volume unknown, approx. 5 cu yd of concrete visible

DESCRIPTION OF RELEASE: Beta/Gamma scan found some contamination on concrete  
slabs. Maximum reading was approx. 1600 cpm. Soil  
Gamma investigation had no elevated findings.

DOCUMENTATION OF NO RELEASE: N/A

RFI NECESSARY: YES



