

UNIT NUMBER SWMU 107

UNIT NAME Rubble pile 5

REGULATORY STATUS: AOC

LOCATION: East of Dykes Road S-1050 W-0700

APPROXIMATE DIMENSIONS: Dam approx. 30 ft long and 20 ft wide - concrete in
and on dam

FUNCTION: Skimming and sampling ditch drainage

OPERATIONAL STATUS: active

DATES OPERATED: 1981 to present

SITE/PROCESS DESCRIPTION: none

WASTE DESCRIPTION: Concrete slabs from plant road construction spoils

WASTE QUANTITY: Approx. 225 cu yards of dam fill and 450 sq ft of concrete
visible

DESCRIPTION OF RELEASE: Contamination found on five different slabs reading
approx. 400 cpm over background. No soil
contamination was found.

DOCUMENTATION OF NO RELEASE: N/A

RFI NECESSARY: YES



