

UNIT NUMBER SWMU 109

UNIT NAME Rubble pile 7

REGULATORY STATUS: AOC

LOCATION: Little Bayou water sampling station at Ogden Landing Road N-0700  
E-2600

APPROXIMATE DIMENSIONS: Concrete slabs irregularly along about 80 ft of creek  
bank

FUNCTION: Erosion control

OPERATIONAL STATUS: In place

DATES OPERATED: 1978-80 to present - additions made in 1980's

SITE/PROCESS DESCRIPTION: Concrete slabs placed along creek bank to control  
bank erosion near water sampling station weir

WASTE DESCRIPTION: Concrete slabs, rubble from plant street maintenance  
program

WASTE QUANTITY: Approx. 500 sq ft of paving

DESCRIPTION OF RELEASE: Beta/Gamma survey found approx. five location with  
readings ranging 150 to 1000 cpm. Soil investigation  
found areas 30 K to 50 K CPM Gama at the three foot  
area above water level

DOCUMENTATION OF NO RELEASE: N/A

RFI NECESSARY: YES



