

UNIT NUMBER SWMU 110

UNIT NAME Rubble pile 8

REGULATORY STATUS: AOC

LOCATION: Abandoned constuction road to C-337 (outside fence) N-0300 W-0900 to W-1200

APPROXIMATE DIMENSIONS: Piles of concrete rubble extend about 240 ft approx.
15 ft wide by 3 ft high

FUNCTION: Store concrete for future use

OPERATIONAL STATUS: inactive

DATES OPERATED: unknown

SITE/PROCESS DESCRIPTION: The site is an abandoned road. The concrete stored is in piles and dumped on both sides of the roadbed.

WASTE DESCRIPTION: Concrete rubble from demolition and reconstruction of plant roads

WASTE QUANTITY: Approx. 200 cu yds

DESCRIPTION OF RELEASE: Beta/Gamma scan found contamination primarily in expansion joint tar that is attached to various slabs of concrete. Approximately 150 cpm over background was an average finding on these areas. Found no detectable soil contamination.

DOCUMENTATION OF NO RELEASE: N/A

RFI NECESSARY: YES



