

UNIT NUMBER SWMU 118

UNIT NAME Rubble pile 16

REGULATORY STATUS: AOC

LOCATION: Big Bayou Water Sampling Station- West Boone Road at Big Bayou
(collapsed bridge) N-2000 W-10200

APPROXIMATE DIMENSIONS: Concrete rubble on creek bank is about 4 ft by 120 ft
of bank (irregular)

FUNCTION: Stabilize bank at water sampling station

OPERATIONAL STATUS: In place - station active

DATES OPERATED: About 1978 to present, concrete rubble was added as needed to
correct erosion

SITE/PROCESS DESCRIPTION: Slabs on bank above and below plume

WASTE DESCRIPTION: Concrete rubble and slabs - probably from PGDP road
upgrading

WASTE QUANTITY: Approx. 20 cu yds of concrete

DESCRIPTION OF RELEASE: Performed Beta/Gamma scan on rubble and found an
average of approx. 80 cpm above background on
4 ft x 8 ft concrete slab

DOCUMENTATION OF NO RELEASE: N/A

RFI NECESSARY: YES



