

UNIT NUMBER SWMU 122

UNIT NAME Rubble pile 20

REGULATORY STATUS: AOC

LOCATION: Ravine culvert (KOW) approx. at S-5400 W-11800

APPROXIMATE DIMENSIONS:

FUNCTION: Erosion control

OPERATIONAL STATUS: In place (trail presently impassable for vehicles)

DATES OPERATED: Past 10 to 15 years

SITE/PROCESS DESCRIPTION: Trail for access to hunting area crosses culvert placed in ravine. Concrete slabs used to construct "roadway" over culvert and placed on faces of roadway.




WASTE DESCRIPTION: Concrete slabs, probably from PGDP

WASTE QUANTITY: Rough estimate, 10 cu yds of concrete

DESCRIPTION OF RELEASE: N/A

DOCUMENTATION OF NO RELEASE: Beta/Gamma survey and soil survey found no elevated readings.

RFI NECESSARY: YES



PHOTOGRAPH NOT AVAILABLE AT THIS TIME

(FOR MORE INFORMATION SEE REBECCA FORSEE)