

UNIT NUMBER SWMU 125

UNIT NAME Rubble pile 23

REGULATORY STATUS: AOC

LOCATION: North of South Acid Road near railroad

APPROXIMATE DIMENSIONS: 200 ft by 200 ft with piles from 1 to 5 ft deep

FUNCTION: Store railroad spoils

OPERATIONAL STATUS: Inactive

DATES OPERATED: Not known, some spoils appear to be 20 to 30 years old -  
concrete curbs were added in last five years

SITE/PROCESS DESCRIPTION: Railroad spoils and curbs cover area along road

WASTE DESCRIPTION: Rails, roadbed, and cross ties from KOW, and perhaps PGDP  
railroads - curbs from parking areas near cascade buildings

WASTE QUANTITY: About 50 cu yds of railroad spoil and 5 cu yds of concrete  
curbing

DESCRIPTION OF RELEASE: All concrete rubble scanned clean except for three  
rusty spots which surveyed out at approx. 2000, 250,  
and 250 cpm. no contaminated soil was found.

DOCUMENTATION OF NO RELEASE: N/A

RFI NECESSARY: YES



