

UNIT NUMBER SWMU 127

UNIT NAME Rubble pile 25

REGULATORY STATUS: AOC

LOCATION: Culvert 1/10 mile north of Heath-Woodville Road on Gravel Pit Road
S-12500, W-8300

APPROXIMATE DIMENSIONS: Roadway 20 ft wide, 25 ft long, and 2 to 16 ft deep

FUNCTION: Ditch crossing and erosion control

OPERATIONAL STATUS: Active

DATES OPERATED: Not known, appears to have been rebuilt in past three years

SITE/PROCESS DESCRIPTION: Concrete used in fill, construction, and for erosion
control for culvert

WASTE DESCRIPTION: Concrete slabs, probably from PGDP

WASTE QUANTITY: Approx. 10 cu yds visible

DESCRIPTION OF RELEASE: N/A

DOCUMENTATION OF NO RELEASE: Rubble survey and soil survey found no detectable
radioactive contamination

RFI NECESSARY: YES



