

UNIT NUMBER SWMU 137

UNIT NAME C-746-A Inactive PCB Transformer Sump Area

REGULATORY STATUS: AOC

LOCATION: East side of C-746-A

APPROXIMATE DIMENSIONS: 12 ft long by 3 ft wide by 3 ft deep

FUNCTION: Secondary containment for transformer, which has been removed

OPERATIONAL STATUS: In place

DATES OPERATED: Mid 1970's to present, The sump valve was tagged with a caution tag on 9/14/90 to prevent any releases prior to characterization.

SITE/PROCESS DESCRIPTION: Concrete dike with sump

WASTE DESCRIPTION: Possible PCB contaminated water

WASTE QUANTITY: Unknown

DESCRIPTION OF RELEASE: Possible migration of PCB contaminated water released to the sewer system through the sump. No releases have been recorded.

DOCUMENTATION OF NO RELEASE: N/A

RFI NECESSARY: YES