

UNIT NUMBER SWMU 141

UNIT NAME C-720 Inactive TCE Degreaser

REGULATORY STATUS: AOC

LOCATION: C-720 Building

APPROXIMATE DIMENSIONS: Approx. 10 ft by 10 ft by 20 ft deep

FUNCTION: Used for cleaning machine parts and equipment

OPERATIONAL STATUS: Inactive

DATES OPERATED: 1970's

SITE/PROCESS DESCRIPTION: The TCE degreaser pit consist of a steel tank approx. 10 ft by 10 ft by 20 ft deep. Located in a basement in C-720 it is raised above the basement floor on stanchions. TCE from the C-720 degreaser was drained via aboveground piping to the C-720 compressor pit water storage tank (swmu #31), which is located outside at the northeast corner of the C-720 Building.

WASTE DESCRIPTION: TCE

WASTE QUANTITY: Unknown

DESCRIPTION OF RELEASE: Possible TCE leakage

DOCUMENTATION OF NO RELEASE: N/A

RF NECESSARY: NO

No releases are known to have occurred at the C-720 Degreaser or from the associated piping. The only release pathway into the environment would be leaks or spills that occurred at the point the aboveground piping associated with the degreaser discharges into the C-720 aboveground tank (swmu #31)). Contamination that was detected in the vicinity of swmu's #31 and 27 is being addressed under the CERCLA ACO.

*The degreaser
was clean closed*