

UNIT NUMBER SWMU 146

UNIT NAME Rubble pile 40

REGULATORY STATUS: AOC

LOCATION: Shelby Lake Dam, about 1000 ft west of Ballard Wildlife Management Area Headquarters

APPROXIMATE DIMENSIONS: 200 ft long, base 300 ft wide, top 20 ft wide, 10 ft deep

FUNCTION: Control Shelby Lake level and provide roadway

OPERATIONAL STATUS: In place

DATES OPERATED: Unknown

SITE/PROCESS DESCRIPTION Ballard Wildlife Management Area utilizes rubble for daam and road stabilization. This concrete rubble originates from many locations, one of which was PGDP.

WASTE DESCRIPTION: Concrete rubble

WASTE QUANTITY: Unknown - Possibly up to 2000 cubic yards. It is also unknown what fraction, if any, of this material came from the PGDP.

DESCRIPTION OF RELEASE: Not available at this time

DOCUMENTATION OF NO RELEASE: Not available at this time

RFI NECESSARY: YES