

UNIT NUMBER SWMU 148

UNIT NAME Rubble Pile 42

REGULATORY STATUS: AOC

LOCATION: Culverts near Burnt Slough, about 1800 ft south of Ohio River at
Burnt Slough

APPROXIMATE DIMENSIONS: Two areas totaled about 100 ft long with concrete
rubble visible on sides

FUNCTION: Roadway stabilization

OPERATIONAL STATUS: In place

DATES OPERATED: Unknown

SITE/PROCESS DESCRIPTION: Ballard Wildlife Management Area utilizes concrete
rubble for dam and road stabilization. This
concrete rubble originates from many locations, one
of which was the PGDP.

WASTE DESCRIPTION: Concrete - concrete block rubble

WASTE QUANTITY: Unknown - appeared to be less than 20 cubic yards. It is also
unknown what fraction, if any, of this material came from the
PGDP.

DESCRIPTION OF RELEASE: Not available at this time

DOCUMENTATION OF NO RELEASE: Not available at this time

RFI NECESSARY: YES