

UNIT NUMBER SWMU 151

UNIT NAME Rubble pile 45

REGULATORY STATUS AOC

LOCATION: West end of Mitche Lake

APPROXIMATE DIMENSIONS: 2000 ft long, 4 ft wide ft thick

FUNCTION: Control erosion on face of dam

OPERATIONAL STATUS: In place

DATES OPERATED: Unknown

SITE/PROCESS DESCRIPTION: Ballard Wildlife Management Area utilizes concrete rubble for dam and road stabilization. This concrete rubble originates from many locations, one of which was the PGDP. The causeway across west end of lake has concrete slabs and rubble on lake side.

WASTE DESCRIPTION: Concrete rubble

WASTE QUANTITY: About 3000 cubic yards. It is also unknown what fraction, if any, of this material came from the PGDP.

DESCRIPTION OF RELEASE: Not available at this time

DOCUMENTATION OF NO RELEASE: Not available at this time

RFI NECESSARY: YES