

UNIT NUMBER: 184

02/22/93

UNIT NAME: Concrete Rubble Pile (29)

REGULATORY STATUS: AOC

LOCATION: Outside plant security south of C-611 Water Treatment Plant.

APPROXIMATE DIMENSION: Estimated to be less than 5 cubic feet.

FUNCTION: Appears to be waste material. The previous use of this material is unknown.

OPERATIONAL STATUS: Inactive

DATES OPERATED Unknown - Unable to determine the length of time the concrete has been at this location.

SITE/PROCESS DESCRIPTION: Two chunks of concrete were found in a wooded area south of C-611. Unable to determine the source of the concrete rubble. Both chunks were half buried.

WASTE DESCRIPTION: Concrete

WASTE QUANTITY: The amount of concrete is estimated to be less than 5 cubic feet. A rad survey of the site did not find any radioactive material present.

DESCRIPTION OF RELEASE: N/A

DOCUMENTATION OF NO RELEASE: Rad survey 92-SP-1831-S did not find any contamination present.

RFI NECESSARY: YES - Even though the rad survey did not identify any contamination present, this unit should be considered as part of the rubble pile investigation. A determination will be made during the initial stages of the RFI investigation as how to best deal with this unit. This is the information available in the ER files at this time.