

UNIT NUMBER: 197

10/21/93

UNIT NAME: CONCRETE RUBBLE PILE (30)

REGULATORY STATUS: AOC

LOCATION: Outside plant security fence, north of the plant on Big Bayou Creek on private property.

APPROXIMATE DIMENSION: Volume is about 1 cubic yard and consist of 20-25 pieces in a 30 feet by 50 feet area.

FUNCTION: Serves as a road bed in a low water crossing.

OPERATIONAL STATUS: Active

DATES OPERATED: The rubble was placed at this location in the late 1980's

SITE/PROCESS DESCRIPTION: The concrete rubble was placed in the creek to serve as a road bed for the crossing. The crossing provides access between fields.

WASTE DESCRIPTION: Concrete rubble.

WASTE QUANTITY: Approximately 1 cubic yard.

DESCRIPTION OF RELEASE: N/A.

DOCUMENTATION OF NO RELEASE: Performed radiological surveys of accessible surface areas. No elevated levels were identified.

RFI NECESSARY: YES - Radiological surveys did not identify any elevated readings. Refer to Survey no. 93-SP-457-S for survey results.