

**PRELIMINARY ASSESSMENT/SITE INSPECTION REPORT
AND SWMU ASSESSMENT REPORT**

UNIT NUMBER: 433

UNIT NAME: S-337-11

DATE: 1/19/2001

REGULATORY STATUS: SWMU

LOCATION: Between columns Sa 26 and Sb 26.

APPROXIMATE DIMENSION: 4 ft. X 4 ft.

FUNCTION: Satellite Accumulation Area (SAA)

BRIEF HISTORY: According to USEC personnel assigned to C-337, these areas were created specifically for waste storage.

OPERATIONAL STATUS: Active

DATES OPERATED: 1993-present. According to USEC operations personnel, this area has been operating from 1993 to present.

SITE/PROCESS DESCRIPTION: Storage area for PCB contaminated vent duct oil.

WASTE DESCRIPTION: PCB vent duct oil

WASTE QUANTITY: Empty as of 12/14/00. The waste quantity is not static since waste is routinely added to the storage area or into individual containers. In addition, waste containers are routinely moved out of the area into RCRA permitted storage for processing prior to treatment and/or disposal

SUMMARY OF ENVIRONMENTAL SAMPLING DATA: None

DESCRIPTION OF RELEASE AND MEDIA AFFECTED: According to USEC operations personnel, there have been no releases to the environment from this SWMU.

GROUNDWATER: N/A

SURFACE WATER: N/A

SOIL: N/A

ECOLOGY AFFECTED (i.e., endangered/threatened species): None

DOCUMENTATION OF NO RELEASE: According to USEC operations personnel, inspection checklists are on file documenting that there have been no releases from this SWMU.

IMPACT ON OR BY OTHER SWMU/AOC: None

PRG COMPARISON: N/A

RFI NECESSARY: No. This unit is being proposed for No Further Action since this SWMU has had no releases to the environment and is not a threat to human health and the environment. According to USEC operations personnel, this unit has been managed and inspected in accordance with approved procedures since its creation.

NOTE: Elements included in this outline shall be considered and incorporated as appropriate, when developing the above referenced document.